

Remarks

Primary riparian vegetation includes: black cottonwood, red and arroyo willow, white alder, and western sycamore. Many bullfrogs were observed in this reach. This reach also has a trapezoidal channel shape that is reinforced by concrete rubble. This reach could be considered function at risk because the Carmel Valley Golf Course is encroaching on the river on the south bank and the north bank is full of concrete rubble preventing natural sinuosity. In addition, Cal-Am's Scarlett well may dewater this area in a dry year.

Summary Determination

Functional Rating:

Proper Functioning Condition	_____
Functional – At Risk	<u> X </u>
Nonfunctional	_____
Unknown	_____

Trend for Functional – At Risk:

Upward	_____
Downward	_____
Not Apparent	_____

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes	<u> X </u>
No	_____

If yes, what are those factors?

<input type="checkbox"/> Flow regulations	<input type="checkbox"/> Mining activities	<input type="checkbox"/> Upstream channel conditions
<input type="checkbox"/> Channelization	<input type="checkbox"/> Road encroachment	<input type="checkbox"/> Oil field water discharge
<input type="checkbox"/> Augmented flows	<input checked="" type="checkbox"/> Other (specify) <u>golf course encroachment and concrete rubble</u>	

