

# Standard Checklist

Name of Riparian-Wetland Area: Cachagua Creek

Date: July 23, 2004 Segment/Reach ID: Reach 15 PFC 401

Miles: \_\_\_\_\_ Elevation: 876 GPS: N 36, 23. 787' W 121, 38. 974'

ID Team Observers: Danica Zupic, Ben Eichorn Time: \_\_\_\_\_

Yes	No	N/A	HYDROLOGY
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	1) Floodplain above bankfull is inundated in "relatively frequent" events
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	2) Where beaver dams are present they are active and stable
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	3) Sinuosity, width/depth ratio, and gradient are in balance with the landscape setting (i.e., landform, geology, and bioclimatic region)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	4) Riparian-wetland area is widening or has achieved potential extent
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	5) Upland watershed is not contributing to riparian-wetland degradation

Yes	No	N/A	VEGETATION
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	6) There is diverse age-class distribution of riparian-wetland vegetation (recruitment for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	7) There is diverse composition of riparian-wetland vegetation (for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	8) Species present indicate maintenance of riparian-wetland soil moisture characteristics
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9) Streambank Vegetation is comprised of those plants or plant communities that have root masses capable of withstanding high-streamflow events
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10) Riparian-wetland plants exhibit high vigor
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11) Adequate riparian-wetland vegetative cover is present to protect banks and dissipate energy during high flows
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	12) Plant communities are an adequate source of coarse and/or large woody material (for maintenance/recovery)

Yes	No	N/A	EROSION/DEPOSITION
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	13) Floodplain and channel characteristics (i.e., rocks, overflow channels, coarse and/or large woody material) are adequate to dissipate energy
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14) Point bars are revegetating with riparian-wetland vegetation
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	15) Lateral stream movement is associated with natural sinuosity
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	16) System is vertically stable
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	17) Stream is in balance with the water and sediment being supplied by the watershed (i.e., no excessive erosion or deposition)

## Summary Determination

### Functional Rating:

Proper Functioning Condition  
Functional—At Risk  
Nonfunctional  
Unknown

<input type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

### Trend for Functional—At Risk:

Upward  
Downward  
Not Apparent

<input type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>

**Are factors contributing to unacceptable conditions outside the control of the manager?**

Yes  
No

<input type="checkbox"/>
<input checked="" type="checkbox"/>

**If yes, what are those factors?**

<input type="checkbox"/> Flow regulations	<input type="checkbox"/> Mining activities	<input type="checkbox"/> Upstream channel conditions
<input type="checkbox"/> Channelization	<input type="checkbox"/> Road encroachment	<input type="checkbox"/> Oil field water discharge
<input type="checkbox"/> Augmented flows	<input type="checkbox"/> Other (specify) _____	



Picture 1



Picture 2



Picture 3

## Remarks

This reach begins at mile marker 6 on Cachagua Road.

The area is predominantly residential, there is minimal riparian wetland vegetative understory, abundant dried algae, several buttressed banks and lots of household garbage to be found (See Picture 1).

There is a summer dam filled in with sediment, with lots of bank erosion nearby (See Picture 2).

Along the roadside several banks are buttressed with boulders and lack vegetative cover, and there are several dirt pushes. There are several eroding banks and an excess of sediment in the creek bed (See Pictures 3 and 4).

At the county bridge at Nason Road, two flow gauges were observed. Both gauges are buried in sediment, one up to the two foot marker, the other up to the four foot mark (See Pictures 5 and 6).

Vegetation thickens toward the confluence with the Carmel River (See Picture 7).

This reach ends at the confluence with the Carmel River, GPS: N36, 24.127, W121, 39.573, elevation 853.

## Checklist Comments

#4,6-12 The willows are healthy but the vegetation is sparse. There are large sycamores, but the understory is sparse and upland species are prominent.

#5,17 There is excessive sediment deposition in this reach.

#15 There is one brief stretch before the confluence with the Carmel River that is split into two equally sized channels, one of which is full of sediment

#16 There are several stabilized banks (three with sandbags, one with a gabion). Currently these banks appear stable, however the risk to lasting vertical stability should not be overlooked.



Picture 4



Picture 5



Picture 6



Picture 7