

Remarks

North bank heavily eroded with no vegetation to protect it. Heavy groundwater extraction in the area is affecting vegetation recruitment and vigor.

Summary Determination

Functional Rating:

Proper Functioning Condition	___
Functional – At Risk	___
Nonfunctional	<u><u>X</u></u>
Unknown	___

Trend for Functional – At Risk:

Upward	___
Downward	<u><u>X</u></u>
Not Apparent	___

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes	<u><u>X</u></u>
No	___

If yes, what are those factors?

<input type="checkbox"/> Flow regulations	<input type="checkbox"/> Mining activities	<input type="checkbox"/> Upstream channel conditions
<input type="checkbox"/> Channelization	<input type="checkbox"/> Road encroachment	<input type="checkbox"/> Oil field water discharge
<input type="checkbox"/> Augmented flows	<input checked="" type="checkbox"/> Other (specify) Groundwater extraction	

