

Remarks

The riverbank by the Quail Lodge Maintenance Building parking lot is susceptible to erosion and currently is only protected by a few riparian trees. Rip-rap in this area has impacted the natural sinuosity. This area is also impacted by groundwater withdrawal from Cal-Am's Cypress Well.

Summary Determination

Functional Rating:

Proper Functioning Condition	_____
Functional – At Risk	<u> X </u>
Nonfunctional	_____
Unknown	_____

Trend for Functional – At Risk:

Upward	_____
Downward	_____
Not Apparent	<u> X </u>

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes	_____
No	_____

If yes, what are those factors?

<input type="checkbox"/> Flow regulations	<input type="checkbox"/> Mining activities	<input type="checkbox"/> Upstream channel conditions
<input type="checkbox"/> Channelization	<input type="checkbox"/> Road encroachment	<input type="checkbox"/> Oil field water discharge
<input type="checkbox"/> Augmented flows	<input type="checkbox"/> Other (specify) _____	

