

Remarks

Primary riparian vegetation includes: black cottonwoods, red and arroyo willows, white alders, and western sycamore. This section received a functional at risk rating because there was a thin band of riparian vegetation associated with old cars as structural bank protection that could fail in a high flow.

This area is also impacted by groundwater extraction by Cal-Am's Cypress Well.

Summary Determination

Functional Rating:

Proper Functioning Condition	_____
Functional – At Risk	____ <u>X</u> ____
Nonfunctional	_____
Unknown	_____

Trend for Functional – At Risk:

Upward	_____
Downward	_____
Not Apparent	_____

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes	_____
No	____ <u>X</u> ____

If yes, what are those factors?

___ Flow regulations	___ Mining activities	___ Upstream channel conditions
___ Channelization	___ Road encroachment	___ Oil field water discharge
___ Augmented flows	___ Other (specify) _____	

