

Remarks

Primary riparian vegetation includes: black cottonwoods, red and arroyo willows, white alders, and western sycamore. This section received a functional at risk rating because there was a thin band of riparian vegetation that could fail in a high flow.

This area is also impacted by groundwater extraction by Cal-Am's Pierce Well.

Summary Determination

Functional Rating:

Proper Functioning Condition	_____
Functional – At Risk	<u> X </u>
Nonfunctional	_____
Unknown	_____

Trend for Functional – At Risk:

Upward	_____
Downward	_____
Not Apparent	_____

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes	_____
No	<u> X </u>

If yes, what are those factors?

<input type="checkbox"/> Flow regulations	<input type="checkbox"/> Mining activities	<input type="checkbox"/> Upstream channel conditions
<input type="checkbox"/> Channelization	<input type="checkbox"/> Road encroachment	<input type="checkbox"/> Oil field water discharge
<input type="checkbox"/> Augmented flows	<input type="checkbox"/> Other (specify) _____	



