

Remarks

Lots of large size class boulders, cobble, and bedrock outcrops to dissipate energy. Riparian species include white alder, Santa Barbara sedge, red and arroyo willows, black cottonwoods, and western sycamore. Residential houses are encroaching on the riparian area.

Summary Determination

Functional Rating:

Proper Functioning Condition	<u> X </u>
Functional – At Risk	<u> </u>
Nonfunctional	<u> </u>
Unknown	<u> </u>

Trend for Functional – At Risk:

Upward	<u> </u>
Downward	<u> </u>
Not Apparent	<u> </u>

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes	<u> </u>
No	<u> X </u>

If yes, what are those factors?

<u> </u> Flow regulations	<u> </u> Mining activities	<u> </u> Upstream channel conditions
<u> </u> Channelization	<u> </u> Road encroachment	<u> </u> Oil field water discharge
<u> </u> Augmented flows	<u> </u> Other (specify) _____	

