



### Remarks

San Clemente Dam is almost completely filled in with sediment. Reservoir drawdown in the spring required by the Department of Safety of Dams has caused an increase in turbidity downstream of the dam in the Carmel River. Riparian plants in this reach consist of white alders, black cottonwoods, sycamores, red, and arroyo willows.

### Summary Determination

Functional Rating:

Proper Functioning Condition	<u>  X  </u>
Functional – At Risk	<u>      </u>
Nonfunctional	<u>      </u>
Unknown	<u>      </u>

Trend for Functional – At Risk:

Upward	<u>      </u>
Downward	<u>      </u>
Not Apparent	<u>      </u>

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes	<u>      </u>
No	<u>      </u>

If yes, what are those factors?

<input type="checkbox"/> Flow regulations	<input type="checkbox"/> Mining activities	<input type="checkbox"/> Upstream channel conditions
<input type="checkbox"/> Channelization	<input type="checkbox"/> Road encroachment	<input type="checkbox"/> Oil field water discharge
<input type="checkbox"/> Augmented flows	<input type="checkbox"/> Other (specify) _____	

