



### Remarks

San Clemente Dam is almost completely filled in with sediment. Reservoir drawdown in the spring required by the Department of Safety of Dams has caused the Carmel River to down cut through the sediment plain behind the dam. This has led to loss of riparian vegetation and the destabilization of banks for approximately a half mile upstream of San Clemente Dam.

### Summary Determination

#### Functional Rating:

Proper Functioning Condition	_____
Functional – At Risk	_____
Nonfunctional	<u>  X  </u>
Unknown	_____

#### Trend for Functional – At Risk:

Upward	_____
Downward	_____
Not Apparent	_____

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes	<u>  X  </u>
No	_____

If yes, what are those factors?

<input type="checkbox"/> Flow regulations	<input type="checkbox"/> Mining activities	<input type="checkbox"/> Upstream channel conditions
<input type="checkbox"/> Channelization	<input type="checkbox"/> Road encroachment	<input type="checkbox"/> Oil field water discharge
<input type="checkbox"/> Augmented flows	<input type="checkbox"/> Other (specify) reservoir operations and sediment	

