



Remarks

Stream reach is just below last house on the way to Pine Creek from Syndicate Camp in the Cachagua area. Vegetation consists of white alder, willows, and sycamores.

Summary Determination

Functional Rating:

Proper Functioning Condition	<u>  X  </u>
Functional – At Risk	<u>      </u>
Nonfunctional	<u>      </u>
Unknown	<u>      </u>

Trend for Functional – At Risk:

Upward	<u>      </u>
Downward	<u>      </u>
Not Apparent	<u>      </u>

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes	<u>      </u>
No	<u>  X  </u>

If yes, what are those factors?

<input type="checkbox"/> Flow regulations	<input type="checkbox"/> Mining activities	<input type="checkbox"/> Upstream channel conditions
<input type="checkbox"/> Channelization	<input type="checkbox"/> Road encroachment	<input type="checkbox"/> Oil field water discharge
<input type="checkbox"/> Augmented flows	<input type="checkbox"/> Other (specify) _____	

