

Standard Checklist

PFC 301

Name of Riparian-Wetland Area: Hitchcock Creek

Date: May 24, 2004 Segment/Reach ID: Reach 1, Mainstem at Rosie's Bridge

Miles: _____ Elevation: 238 GPS: N 36, 28. 434' W 121, 43. 589'

ID Team Observers: Clive Sanders, Danica Zupic Time: _____

Yes	No	N/A	HYDROLOGY
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	1) Floodplain above bankfull is inundated in "relatively frequent" events
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	2) Where beaver dams are present they are active and stable
<input checked="" type="checkbox"/>	<input type="checkbox"/>		3) Sinuosity, width/depth ratio, and gradient are in balance with the landscape setting (i.e., landform, geology, and bioclimatic region)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	4) Riparian-wetland area is widening or has achieved potential extent
<input checked="" type="checkbox"/>	<input type="checkbox"/>		5) Upland watershed is not contributing to riparian-wetland degradation

Yes	No	N/A	VEGETATION
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	6) There is diverse age-class distribution of riparian-wetland vegetation (recruitment for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	7) There is diverse composition of riparian-wetland vegetation (for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	8) Species present indicate maintenance of riparian-wetland soil moisture characteristics
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9) Streambank Vegetation is comprised of those plants or plant communities that have root masses capable of withstanding high-streamflow events
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10) Riparian-wetland plants exhibit high vigor
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11) Adequate riparian-wetland vegetative cover is present to protect banks and dissipate energy during high flows
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	12) Plant communities are an adequate source of coarse and/or large woody material (for maintenance/recovery)

Yes	No	N/A	EROSION/DEPOSITION
<input checked="" type="checkbox"/>	<input type="checkbox"/>		13) Floodplain and channel characteristics (i.e., rocks, overflow channels, coarse and/or large woody material) are adequate to dissipate energy
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14) Point bars are revegetating with riparian-wetland vegetation
<input checked="" type="checkbox"/>	<input type="checkbox"/>		15) Lateral stream movement is associated with natural sinuosity
<input checked="" type="checkbox"/>	<input type="checkbox"/>		16) System is vertically stable
<input checked="" type="checkbox"/>	<input type="checkbox"/>		17) Stream is in balance with the water and sediment being supplied by the watershed (i.e., no excessive erosion or deposition)

Summary Determination

Functional Rating:

Proper Functioning Condition
Functional—At Risk
Nonfunctional
Unknown

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Trend for Functional—At Risk:

Upward
Downward
Not Apparent

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes
No

<input type="checkbox"/>
<input type="checkbox"/>

If yes, what are those factors?

Flow regulations Mining activities Upstream channel conditions
 Channelization Road encroachment Oil field water discharge
 Augmented flows Other (specify) _____



Remarks

This reach is at the confluence of Hitchcock Creek and the Carmel River, it is in proper functioning condition. There was a diverse age-class distribution and composition of vegetation. There seemed to be adequate riparian vegetative cover and channel characteristics to dissipate high flow energy. There was no excessive erosion or deposition.

The road side bank is a steep slope that is currently being shored up by large rocks.

There is a large pile of loose brush/ yard waste that was dumped on a 100ft wide area of the downstream, road side bank (See Picture 1).

Checklist Comments

#16 The road side bank is now stable for now and is currently being shored up by large rocks.