

Standard Checklist

Name of Riparian-Wetland Area: James Creek

Date: August 18, 2004 Segment/Reach ID: Reach A PFC 505

Miles: _____ Elevation: _____ GPS: N 36, 21. 747' W 121, 35. 529

ID Team Observers: Clive Sanders, Danica Zupic Time: _____

Yes	No	N/A	HYDROLOGY
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	1) Floodplain above bankfull is inundated in "relatively frequent" events
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	2) Where beaver dams are present they are active and stable
<input checked="" type="checkbox"/>	<input type="checkbox"/>		3) Sinuosity, width/depth ratio, and gradient are in balance with the landscape setting (i.e., landform, geology, and bioclimatic region)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	4) Riparian-wetland area is widening or has achieved potential extent
<input checked="" type="checkbox"/>	<input type="checkbox"/>		5) Upland watershed is not contributing to riparian-wetland degradation

Yes	No	N/A	VEGETATION
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	6) There is diverse age-class distribution of riparian-wetland vegetation (recruitment for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	7) There is diverse composition of riparian-wetland vegetation (for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	8) Species present indicate maintenance of riparian-wetland soil moisture characteristics
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9) Streambank Vegetation is comprised of those plants or plant communities that have root masses capable of withstanding high-streamflow events
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10) Riparian-wetland plants exhibit high vigor
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11) Adequate riparian-wetland vegetative cover is present to protect banks and dissipate energy during high flows
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	12) Plant communities are an adequate source of coarse and/or large woody material (for maintenance/recovery)

Yes	No	N/A	EROSION/DEPOSITION
<input checked="" type="checkbox"/>	<input type="checkbox"/>		13) Floodplain and channel characteristics (i.e., rocks, overflow channels, coarse and/or large woody material) are adequate to dissipate energy
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14) Point bars are revegetating with riparian-wetland vegetation
<input checked="" type="checkbox"/>	<input type="checkbox"/>		15) Lateral stream movement is associated with natural sinuosity
<input checked="" type="checkbox"/>	<input type="checkbox"/>		16) System is vertically stable
<input checked="" type="checkbox"/>	<input type="checkbox"/>		17) Stream is in balance with the water and sediment being supplied by the watershed (i.e., no excessive erosion or deposition)

Summary Determination

Functional Rating:

Proper Functioning Condition
Functional—At Risk
Nonfunctional
Unknown

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Trend for Functional—At Risk:

Upward
Downward
Not Apparent

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes
No

<input type="checkbox"/>
<input type="checkbox"/>

If yes, what are those factors?

Flow regulations Mining activities Upstream channel conditions
 Channelization Road encroachment Oil field water discharge
 Augmented flows Other (specify) _____

Remarks

This reach began at a private gate off of a dirt cut road. There are many large healthy maples, sycamores and buckyeyes. However, there are not a lot of small riparian plants or willows in this reach. Despite this lack the area has adequate cover to withstand and dissipate a large stream flow event.

There is an accessible floodplain that is mainly vegetated by upland species and (currently) dry grasses.

Despite the close proximity of the dirt cut road there is not excess sediment found in this reach. Large cobbles and rocks are clearly visible throughout the creekbed in this reach.

There is plenty of LWD and boulders to dissipate energy in this reach.

This reach ended on Tassajara Rd. at GPS: N 36,21.965
W121,35.363

Checklist Comments

#9, 11 There are lots of mature well rooted trees, however smaller riparian plants are scarce.