

Standard Checklist

Name of Riparian-Wetland Area: San Clemente Creek (San Clemente Rancho)

Date: May 18, 2004 Segment/Reach ID: Reach 6, Cabin #3 Durbin's PFC 606

Miles: _____ Elevation: 1030 GPS: N 36, 25. 475' W 121, 44. 606'

ID Team Observers: Clive Sanders, Danica Zupic Time: _____

Yes	No	N/A	HYDROLOGY
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	1) Floodplain above bankfull is inundated in "relatively frequent" events
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	2) Where beaver dams are present they are active and stable
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	3) Sinuosity, width/depth ratio, and gradient are in balance with the landscape setting (i.e., landform, geology, and bioclimatic region)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	4) Riparian-wetland area is widening or has achieved potential extent
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	5) Upland watershed is not contributing to riparian-wetland degradation

Yes	No	N/A	VEGETATION
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	6) There is diverse age-class distribution of riparian-wetland vegetation (recruitment for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	7) There is diverse composition of riparian-wetland vegetation (for maintenance/recovery)
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	8) Species present indicate maintenance of riparian-wetland soil moisture characteristics
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	9) Streambank Vegetation is comprised of those plants or plant communities that have root masses capable of withstanding high-streamflow events
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10) Riparian-wetland plants exhibit high vigor
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	11) Adequate riparian-wetland vegetative cover is present to protect banks and dissipate energy during high flows
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	12) Plant communities are an adequate source of coarse and/or large woody material (for maintenance/recovery)

Yes	No	N/A	EROSION/DEPOSITION
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	13) Floodplain and channel characteristics (i.e., rocks, overflow channels, coarse and/or large woody material) are adequate to dissipate energy
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14) Point bars are revegetating with riparian-wetland vegetation
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	15) Lateral stream movement is associated with natural sinuosity
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	16) System is vertically stable
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	17) Stream is in balance with the water and sediment being supplied by the watershed (i.e., no excessive erosion or deposition)

Summary Determination

Functional Rating:

Proper Functioning Condition
Functional—At Risk
Nonfunctional
Unknown

<input type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Trend for Functional—At Risk:

Upward
Downward
Not Apparent

<input type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes
No

<input type="checkbox"/>
<input checked="" type="checkbox"/>

If yes, what are those factors?

Flow regulations

Channelization

Augmented flows

Mining activities

Road encroachment

Other (specify) _____

Upstream channel conditions

Oil field water discharge

Remarks

Picture 1



There is an eroding hillside, an eroding bank opposite of the cabin and an eroding bank under the deck of the cabin (See Picture 1 and 2). At the base of the naturally eroding hillside is a grassy floodplain that lacks strong rooted plants. There is a large fallen tree that seems to be helping to catch the dropping sediment and debris and helping to stabilize the base of the hillside. The eroding bank by the cabin has been shored up with rocks and concrete. There is a large point bar forming directly opposite of this concrete structure.

Twenty feet downstream from the cabin the river is in PFC.



Picture 2

Checklist Comments

#5, 17 There is excessive sediment in the creek forming a point bar on the bank opposite the cabin. This excess sediment may be from new road and house construction outside of the owners property.

#9, 11, 13 The lack of a large strong root system in the small floodplain across from the house puts the system at risk.

#16 The system is not vertically stable where both banks are eroding and the bank directly behind the cabin is being shored up.

Picture 3

