



Remarks

Primary riparian vegetation includes: black cottonwood, red and arroyo willow, white alder, and western sycamore. This reach is constrained on the south bank because of Carmel Valley Golf Course. In addition, Cal-Am's Scarlett well may dewater this area in a dry year.

Summary Determination

Functional Rating:

|                              |               |
|------------------------------|---------------|
| Proper Functioning Condition | <u>  X  </u>  |
| Functional – At Risk         | <u>      </u> |
| Nonfunctional                | <u>      </u> |
| Unknown                      | <u>      </u> |

Trend for Functional – At Risk:

|              |               |
|--------------|---------------|
| Upward       | <u>      </u> |
| Downward     | <u>      </u> |
| Not Apparent | <u>      </u> |

Are factors contributing to unacceptable conditions outside the control of the manager?

|     |               |
|-----|---------------|
| Yes | <u>      </u> |
| No  | <u>  X  </u>  |

If yes, what are those factors?

|   |  |  |
|---|--|--|
| <input type="checkbox"/> Flow regulations | <input type="checkbox"/> Mining activities     | <input type="checkbox"/> Upstream channel conditions |
| <input type="checkbox"/> Channelization   | <input type="checkbox"/> Road encroachment     | <input type="checkbox"/> Oil field water discharge   |
| <input type="checkbox"/> Augmented flows  | <input type="checkbox"/> Other (specify) _____ |  |

