



Remarks

Large boulders and cobble exist to dissipate energy. Riparian species include white alder, Santa Barbara sedge, and western sycamore.

Summary Determination

Functional Rating:

Proper Functioning Condition	<u>  X  </u>
Functional – At Risk	<u>      </u>
Nonfunctional	<u>      </u>
Unknown	<u>      </u>

Trend for Functional – At Risk:

Upward	<u>      </u>
Downward	<u>      </u>
Not Apparent	<u>      </u>

Are factors contributing to unacceptable conditions outside the control of the manager?

Yes	<u>      </u>
No	<u>  X  </u>

If yes, what are those factors?

<u>  </u> Flow regulations	<u>  </u> Mining activities	<u>  </u> Upstream channel conditions
<u>  </u> Channelization	<u>  </u> Road encroachment	<u>  </u> Oil field water discharge
<u>  </u> Augmented flows	<u>  </u> Other (specify) _____	

